ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0667, W0663, W0679, W0655, W0344, W0653, W0677, W	NA	Thirumalanagara ABCD Blocked
Segment No.	**Total Length (m)**	
3/C-W0667/S123220	436.46	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	283.18	77.565577	13.099687	77.564590	13.097707	M0008	DEAD END
2	153.28	77.566409	13.099092	77.565014	13.099316	W0653	W0299

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Asphalting of roads and drain at Thirumalanagara ABCD Blocked in ward no 03 Yelahanka Satellite Town Sub division Yelchanka zone	5000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	Asphalting of roads and drain
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to Asphalting of roads and drain at Thirumalanagara ABCD Blocked in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone	003-17-000073
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/ (YNK.D)/WO/116/2017 -18	07/11/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/12/2017	19/12/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0667, W0663, W0679, W0655,

ಸಹಾಯಕ ಅಭಿಯಂತರರು, ವಾರ್ಡ್ ಸಂ-03
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು – 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Phone No.	E-Mail ID
9449863065	

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0667, W0663, W0679, W0655,

ಸಹಾಯಕ ಅಭಿಯಂತರರು, ವಾರ್ಡ್ ಸಂ-23
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು – 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬ.ಬ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

ld Inspection Details

Number of Trees	Any Other Information	Name
6		chandrakanth
Date of Inspection	**Remarks**	
23/12/2017	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alturu **Street ID:** W0667, W0663, W0679, W0655,

ಸಹಾಯಕ ಅಧಿಯಂತರರು, ವಾರ್ಡ್ ಸಂ-03
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು - 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0667, W0663, W0679, W0655,

ಸಹಾಯಕ ಆಭಿಯಂತರರು, ವಾರ್ಡ್ ಸಂ-03
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು – 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಜಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-105